

BERSCH & ASSOCIATES LTD.

November 21, 2016

City of Saskatoon
Facilities & Fleet Management
3130 Laurier Drive
Saskatoon, SK
S7L 5J7

ATTENTION: Darrell Wasylowich

SUBJECT: Bulk Sample Analysis Report STS – 226 - 23rd Street East, Saskatoon, SK.

Please find attached our laboratory's results for the bulk sample collected November 14, 2016 from Saskatoon Transit Services - Customer Services Centre. The sample of the ceiling tile was sampled for the identification of asbestos. Asbestos **was not** detected within the sample.

The results for the sample submitted was obtained by examination in accordance with the current USEPA 600/R-93/116 Method for the analysis of asbestos in building materials using polarized light microscopy and dispersion staining techniques. The detection limit of this method is listed as less than 1% by volume.

This test report relates only to the materials sent for examination and any use or extension of the information by the client of these results is the responsibility of the client.

If any questions arise on the results of the attached information, please contact our office. Thank you for this opportunity of service!

Sincerely,



Brad Berschiminsky
Bersch & Associates Ltd.

File No. – B67BLK14F sts

Bersch & Associates Ltd.

B67BAK14F

Box 3568
Humboldt, Sask. S0K 2A0

BULK SAMPLE ANALYSIS REPORT

PROJECT NO: B67.16
CLIENT: CITY OF SASKATOON
CONTACT: DARRELL WASYLOWICH
LOCATION: SASKATOON TRANSIT SERVICES - CUSTOMER SERVICES CENTRE

NO.	DATE	SAMPLE INFORMATION	ASBESTOS	%	ANALYST
1	14-Nov-16	Computer / Locker Room - 2' X 4' Suspended Ceiling Tile	No Asbestos Detected		WB